Inf Oct. 20

Work Orde June 4, 2010 11.		65	LVGALAN									Page 1
Revision ID:	D4122-1 Floor Protector,	PRELIN Fwd	MARY	Haccept Kul					Setup	Start Stop		
Start Date: Required Date: Reference:		Start Qty: 3.00 Req'd Qty: 3.00	1188188 (Cust Item I Customer:	D:						
Approvals:	Process Plan	:: <u> </u>	Date:	Tooling:	. D	ate:			Run	Start		
	QC:		Date:	SPC (Y/N):	D	ate:				Stop		
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revis	sion Nbr										
D4122		3		0.00			. <u> </u>					
		FLOW WATER JET						R	(0-16	770	2	
Waterjet FLOW CNC Waterje	et .	Memo 1-Cut as Dwg Rev Prog Rev 2-Deburr	<u> </u>	0.00								3
110		QC2- Inspect parts of	f machine FAI/FAIB	0.00								
QC Quality Control		Memo		0.00				比心	7-10-	-30		
120 		QC8- Inspect parts - s	second check	0.00				9				
QC Quality Control		Memo	vo eev. B + stompæl etenseel, A10.10.20	0.00		·						100000 HOUB
		r	A10.10.50			•						

Dart	Aer	ost	pace	Ltd
------	-----	-----	------	-----

										3
W/O:			WO	RK ORDER CHA	NGES		·			
DATE	STEP	PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,						İ	
Part No		PAR #:								
	Res	olution:	Disposition	ı:	QA	: N/C Cld	sed:	·	Date:	
NCR:			WORK ORDE	R NON-CONFO	RMANCE	(NCR)			
DATE	STEP	Description of NC	Corrective Action Section B			Verification		Approval	Approval	
		Section A	Initial Chief Eng	Action Descript Chief Eng	ion	Sign & Date	Section	on C	Chief Eng	QC Inspector
1									,	

NOTE: Date & initial all entries

Work Order ID 59465

Page 2

June 4, 2010 11:51:36 AM

Item ID:

D4122-1

Accept

Setup Start

Stop



Revision ID:

Item Name:

Floor Protector, Fwd

Start Date:

6/10/10

Start Qty: 3.00

Required Date: 6/14/10

Req'd Qty: 3.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Tool ID

Start Run

QC:

Date:

SPC (Y/N):

Date:

Stop

Insp.

Stamp

Reject

Number

Sequence ID/ **Work Center ID**

130

Small Fab

Small Fab

Operation Description

Small Fab

Memo

Memo

Memo

Deburr if necessary.

Set Up/ Run Hours

0.00

0.00

Tool # Plan

Code

Reject

Qty

140 QC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

0.00

Accept

Qty

150

Packaging

Packaging

Identify as per dwg & Stock Location:

0.00

0.00

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
						-			
								·	
Part No):	PAR #:	Fault Categ	ory:	NCR: Yes	No DQA	\ :	Date:	
Resolution: Disposition:				QA: N/C Closed: Date:					
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	₹)			
DATE	STEP	Description of NC			tion B	Verific	ation	Approval Chief Eng	Approval QC Inspector
	J	Section A	Initial Chief Eng	Action Description Chief Eng	Sign a		Section C		
			3						
<u>.</u>									
	 								
									:

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Picklist Print

June 4, 2010 11:51:35 AM

Work Order ID: 59465

Parent Item: D4122-1

Parent Item Name: Floor Protector, Fwd

Comments:

1PP Rev:A 10.06.04 new issue DD verf:JLM



Start Date: 6/10/10

Required Date: 6/14/10

Page 1

Start Qty: 3.00

Required Qty: 3.00

1810-10-20

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MLEXS.125-F60029-04		Purchased	No			100	sf	1,762.106	27.143	85 71474			

GE PLASTICS LEXAN SHEET

Location	Loc Qty	Loc Code		
MAT	1762.1068			(2)
111710	64			\odot
112585	165.783			
114032	1532.3238			
115261			115 2/-1	

Dart Aerospace Ltd

W/O:			V	ORK ORDER CH	HANGES					
DATE	STEP	PROC	EDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•						
					84. 8					
Part No		PAR #:								
	Re	esolution:	_ Disposit	ion:	QA	: N/C Cld	sed:		Date:	
NCR:	•	W	ORK OR	DER NON-CONF	ORMANCE	(NCR)			7.0
DATE	STEP	Description of NC	Corrective Action Section B			Verifi		cation Approx	Approval	Approval
	SILI	Section A	Initial Chief Eng	Action Descr Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
l										
		,								
							· · ·			
			}							
	<u> </u>								•	

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	59465
Description: Floor PROTECTOR FWD	Part Number:	D4132-1
Inspection Dwg: DU() 2~1 Rev: R		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article		Prototype
---	---------------	--	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
7	400 - 01	3,008	<i>t</i>		U 1802	
	7.00 - 001 7- 030	1.480	عد	þ	V	
2,76	7030	276	W		T 1301	
3.70	1/ 30	3,70	×	,	٦	
9.63	7/ -330	9.63	<u>م</u>		7	
16.00	4030	16.00	T		7	
96.76	4 .00	27.26			7	·
2776	4-530	27,76	<u>a</u>		T T	
31,00	TL .30 T32	31.00	8		7	
34,51 41.88	4 30 41.9	34.50	2		7	
73.60	L :30	73,00	Dr -		7	
78.78	L	78.78	1		7	
83.66	1	83.66	70		7	
6.65		6.65	7		7	
11.53	th 330	11.42	4		1	
15.92		15.97	×	<u> </u>	7	
35,15		3511	٦	-	7	
35.65	1	35.65	4		7	
57.65		57,65	b		T	
58.15		58.16	10	 	7	
77.40	7L .030	71.40	0		7	

Measured by: Audited by: Prototype Approval: N/A Peuß

Date: 040-20 Date: 10:1020 Date: N/A

		Re	vised by	Approved
Rev	Date	Clianue		
1101		New Issue KJ/	JLM	1
- I A I		New issue		* •

DART ASPOSPACE LTD	Work Order:	59465
DART AEROSPACE LTD		
Description: FLOOR PROTECTOD FUID	Part Number:	D4122-(
Inspertion Dwg: D4(3)~(Rev: B		Page 1 of 1

	X First Article			Prototype			
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Com	ments
86.65	1- 030	86.60	r		T 1301		
93,29	4. 30	93.29	>	*	7		
.125	7/010	1131	حد		V 1302		
.,,,,							
			-				
		·					
							je je
	+						
		*					
				7			
leasured by:		Audited by:			Prototype Approval:		N/A
Date:	10-10-30	Date:	1010	170		Date:	N/A





